



1097 Foxen Canyon Road • Santa Maria, CA 93454  
805-922-1202 Telephone • 805-922-1084 Fax  
mark@ajpe.net

**To all TFX and 481-X users:**

## **H-11 Tool Steel Main & Head Stud Alert!**

***If H-11 Tool Steel studs are allowed in contact with water or moisture while in a torqued condition (tension),***

***Chances are good that they will FAIL!***

**Please do NOT wash your blocks with Water (or water based cleaners) with the Main Caps & Studs installed on the block.**

H-11 Tool Steel Main Studs can be verified by the presence of a .250" internal hex broached in the 9/16-18 end (fine thread end).

We recommend that you remove the H-11 Main Studs & wash them with a Non-water based cleaner, i.e.: Solvent or Brake Cleaner.

After washdown, be sure to completely dry the studs, & then spray them with a rust preventative oil based product like: WD-40, JB-80, LPS-2, or similar.

If you have any questions please call: **Mark Meza at AJPE (805) 922-1202**